




























	PART NO	DESCRIPTION	VEHICLE	PRICE
	955512-2	Door Skin, Right	T2 BAY	€65.00
	955580-0	Front Cross Member	T2 BAY	€28.00
	955581-1	Jacking Point	T2 BAY	€17.00
	955581-2	Jacking Point	T2 BAY	€17.50
	955584-2	Jacking Point	T2 BAY	€19.50
	955583-1	Jacking Point, rear left	T2 BAY	€20.00
	955583-2	Jacking Point, rear right	T2 BAY	€20.00
	955579-0	Jacking Point	T2 BAY	€17.50
	955578-1	Jacking Point Front Left	T2 BAY	€27.50
	955635-1	B frame repair piece	T2 BAY	€12.50
	955635-2	B frame repair piece	T2 BAY	€10.00
	955502-1	Sill, NOT Slider side	T2 BAY	€22.85
	955502-2	Sill, Slider side	T2 BAY	€22.85
	955506-1	Inner Sill, Left	T2 BAY	€27.75
	955506-2	Inner Sill, Right	T2 BAY	€25.75
	955507-2	Inner door sill	T2 BAY	€25.00
	955585-0	Crossmember bottom	T2 BAY	€15.50

	955500-2	Sill Right	T2 BAY	€25.00
	955500-1	Sill Left	T2 BAY	€22.50
	955517-0	Door body repair section	T2 BAY	€15.00
	955531-1	Front Wheel Arch. Left	T2 BAY EARLY	€115.00
	955524-1	Cab Step Inner part, left	T2 BAY EARLY	€15.00
	955524-2	Cab Step Inner part, right	T2 BAY EARLY	€15.00
	955538-1	Inner wing repair panel, left	T2 BAY EARLY	€12.85
	955538-2	Inner wing repair panel right	T2 BAY EARLY	€12.85
	955575-0	Floor Section	T2 BAY EARLY	€35.00
	955606-1	Sill inner section	T2 BAY EARLY	€41.45
	955533-2	Front Wheel Arch Right	T2 BAY EARLY	€19.50
	955533-1	Front Wheel Arch Left	T2 BAY EARLY	€19.50
	955520-0	Front cowling, lower section	T2 BAY EARLY	€45.00
	955074	Cover plate, Bellow Pedals	T2 BAY LATE	€45.00
	955680-0	Front Cross Rail	T2 BAY LATE	€20.00
	955632-1	Cab Step, left outer part	T2 BAY LATE	€23.70
	955656-1	Wheel arch repair, front of rear arch left	T2 BAY LATE	€15.00
	955656-2	Wheel arch repair, front of rear arch right	T2 BAY LATE	€15.00

	955569-0	Battery Tray	T2 BAY LATE	€24.00
	955624-2	Front Cab Step INNER PART Right	T2 BAY LATE	€22.00
	955624-1	Front Cab Step INNER PART Left	T2 BAY LATE	€22.00
	955660-1	Quarter panel rear left	T2 BAY LATE	€19.19
	955660-2	Quarter panel rear right	T2 BAY LATE	€17.50
	955631-1	Wheel Arch Front Left	T2 BAY LATE	€110.00
	955633-1	Front Wheel Arch LEFT	T2 BAY LATE	€21.00
	955631-3	Front Wheel Arch LEFT	T2 BAY LATE	€22.50
	955631-4	Front Wheel Arch RIGHT	T2 BAY LATE	€21.00
		SPLIT		
	955560-1	Rear wheel arch section, left	T2 BAY-SPLIT	€14.95
	955560-2	Rear wheel arch section, right	T2 BAY-SPLIT	€14.95
	955559-1	Rear Wheel Arch Early Bay and Split	T2 BAY-SPLIT	€29.00
	955031-1	Front Wheel Arch	T2 SPLIT	€99.00
	955082-0	Front Cross Member	T2 SPLIT	€21.25
	955056-2	sill repair short	T2 SPLIT	€18.50
	955069-0	Battery Tray	T2 SPLIT	€20.65
	955081-0	Rear Cross Rail	T2 SPLIT	€17.00

	9550230	Front Cowling	T2 SPLIT	€78.00
	955002-2	Sill under cargo doors, split	T2 SPLIT	€32.50
	955020-0	Front panel	T2 SPLIT	€269.00
	955075-1	Body Floor Cargo Area Outer	T2 SPLIT	€99.00
		T25		
	955723-1	Front panel, lower, for aircooled	T25	€129.90
	955717-0	Slider bottom, Inner	T25	€32.00
	955759-4	Rear Wheel Arch, Rear	T25	€37.50
	955733-1	Front Wheel arch, left	T25	€29.90
	955724-0	Front Panel Upper	T25	€110.00
	955733-2	Front wheel arch, right	T25	€27.50